

SECRET

OUT56837

1965 OCT 4 16 56Z

1

multi

P 041632Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/20 RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5589.

Declassification Review by NGA/DoD

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

04 OCT 1965

1. CAMERA B 7 WAS USED IN MISSION 8046 FLOWN ON 30 SEPTEMBER
 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE. THE RESOLUTION IS GOOD;
 HOWEVER, THE 1L AND 1R POSITIONS ARE LESS SHARP THAN THE VER-
 TICALS. THE 1L POSITIONS ARE WORSE THAN THE 1RS.

B. 9R SIDE: SLIGHT EDGE STATIC IS PRESENT ALONG BOTH
 EDGES THROUGHOUT THE MISSION. INBOARD ROLLER CHATTER BEGINS IN
 FRAME 1518 AND CONTINUES TO THE END OF THE MISSION. A ROW OF
 MINUS DENSITY DOTS 4.55" APART AND 0.8" FROM THE INBOARD EDGE
 IS PRESENT FROM HEAD TO TAIL. A SERIES OF MINUS DENSITY DOTS
 WHICH FORM AN IRREGULAR 0.1" DIAMETER CIRCLE IS PRESENT ON FRAMES
 2303 THROUGH 2359. THE CENTER OF THIS CONFIGURATION OF MINUS
 DENSITY DOTS IS LOCATED 0.3" FROM THE INBOARD EDGE AND THE SERIES
 APPEARS APPROXIMATELY EVERY 18.0". TWO PLUS DENSITY SPOTS ARE
 PRESENT WITHIN THE MINUS DENSITY CONFIGURATION THE LAST TIME IT

COPIES RECEIVED		
Cy No.	Office	Act.
1	EdJ	
2	CS	
	Z...	
	S...	
	F...	
	CD	
	LD	
	ED	
	FD	
	FD	
34	FD	✓
	FD	
	PAG	
	DIA-4	
	SPAD	
	NSA-10	
	DIA-AP	

1

-2-

APPEARS. THESE PLUS DENSITY SPOTS THEN OCCUR EVERY 4.6" IN FRAMES 2359 THROUGH 2402. ANOTHER SERIES OF MINUS DENSITY DOTS 2.3" APART AND 0.5" FROM THE INBOARD EDGE IS PRESENT ON FRAMES 2252 THROUGH 2332. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 2227.

C. 9L SIDE: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ON BOTH SIDES THROUGHOUT THE MISSION. METERING IS IRREGULAR RANGING FROM 0.25" TO 0.6". THE VERTICAL DOT INDICATOR IS BLOOMED. THE IL POSITION INDICATOR IS UNDEREXPOSED. LONGITUDINAL PLUS DENSITY STREAKS ARE PRESENT 4.1" AND 4.3" FROM THE INBOARD EDGE ON FRAMES 220, 224, AND 227. IRREGULAR MINUS DENSITY STREAKS ARE PRESENT ON THE INBOARD EDGE OF FRAMES 1663 TO 1669. DEPOSITS OF EXCESS DYE AND TITLE FLAKING IS PRESENT ON SEVERAL FRAMES. WAX ON THE TITLED EDGE IS SMEARED ON FRAMES 1701 TO 1719. EMULSION LIFTS ARE LOCATED IN FRAMES 2108, 2190, AND 2203. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 1671 AND ASSOCIATED PLUS DENSITY AREAS ARE PRESENT ON FRAMES 1668/1669 AND 1673.

D. BOTH SIDES: MANY SOFT AND SMEARED FRAMES CAUSED BY VEHICLE TURN MANEUVERS WERE NOTED. THE FIRST AND LAST TITLED FRAMES ON EACH SIDE ARE 0000 AND 2404.

E. THERE WERE NO MAJOR PROCESSING ANOMALIES OR CAMERA MALFUNCTIONS IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 15 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-